

Service History Summary

Mazda3 1.5 SKYACTIV-G 100hp · 6-speed manual · Soul Red

REGISTRATION	FIRST REGISTERED	ODOMETER	NCT VALID TO
172-D-19940	29 September 2017	83,302 km	28 Sep 2027

10 documented visits	2017–2026 serviced every year, no gaps	9,250 km average per year
-------------------------	---	------------------------------

DATE	ODOMETER	GARAGE	WORK CARRIED OUT
Sep 2017	8 km	J A Boland Mazda, Carlow	Pre-delivery inspection · body inspection
Sep 2018	11,138 km	Joe Duffy Mazda, Dublin 11	1st scheduled service · body inspection
Sep 2019	23,501 km	Joe Duffy Mazda, Dublin 11	2nd scheduled service · body inspection
Sep 2020	32,725 km	Joe Duffy Mazda, Dublin 11	3rd scheduled service · body inspection
Sep 2021	44,582 km	Coolmine Motors, Dublin 15	Oil (0W20), oil filter, air filter · vehicle inspection
Sep 2022	not recorded	Coolmine Motors, Dublin 15	Annual service · front brake pads · 2 new tyres 205/60 R16
Jun 2023	62,350 km (from NCT)	Coolmine Motors, Dublin 15	Annual service
Jun 2024	not recorded	Coolmine Motors, Dublin 15	Annual service
Jun 2025	78,336 km (from NCT)	Coolmine Motors, Dublin 15	Annual service · rear coil spring, front suspension arm, 2 rear stabiliser links, wheel alignment
Jun 2026	not recorded	Coolmine Motors, Dublin 15	Annual service · 2 new tyres 205/60 R16 · rear brake pads

Figures marked (from NCT) are official National Car Test odometer readings. Across all tests (2021: 44,864 km · 2023: 62,350 km · 2025: 78,336 km) the mileage rises consistently — independently confirmed, no discrepancies.

RECENT WORK

Jun 2026	Two new tyres (205/60 R16) and rear brake pads, fitted alongside the annual service.
Jun 2025	Suspension refresh — rear coil spring, front suspension arm, two rear stabiliser links and four-wheel alignment.
Sep 2022	Front brake pads and two new tyres (205/60 R16).

Approximately €1,320 invested in the last fourteen months. Tyres, brakes and suspension are all recently done.

Every entry above is backed by paperwork. The 2017–2020 services are on the official Mazda Digital Service Record for this car; the 2021–2026 services are original Coolmine Motors invoices, all quoting registration 172-D-19940. NCT certificates and reports for 2021, 2023 and 2025 are included in this pack. Everything is available to view and comes with the car.

Coolmine Motors LTD

Unit 46 c Coolmine Industrial Estate

Blanchardstown, Dublin 15

Mobile: 0860488100/0877631513

Phone: 018228436

Email: info@coolminemotors.ieWeb: www.coolminemotors.ie

VAT Number: IE9754664N



Date:

24/06/2026

Invoice No:

55439

Invoice to**Vehicle details**

Make:

Mazda

Reg. No

172D19940

Milage

Model :

3

Engine

1.6

Description:

2 tyres 205/60R16, service a, rear brake pads

	Qty	Net	Vat	Total
Parts 13.5 %		158.59	21.41	180.00
<u>Tyres</u>	2	227.64	52.36	280.00
Batteries		0.00	0.00	
Accessories		0.00	0.00	
Labour 13.5 %		185.02	24.98	210.00
VEMC Charge Car / Van / 4x4	2	5.60	1.29	6.89

All good shall remain the property of MJ Coolmine Motors Ltd
untill paid in full.

Included in this a visible Environmental Management Cost - VEMC.

Total Net 571.25

Total VAT 98.75

Total 670.00

Coolmine Motors LTD

Unit 46 c Coolmine Industrial Estate

Blanchardstown, Dublin 15

Mobile: 0860488100/0877631513

Phone: 018228436

Email: info@coolminemotors.ieWeb: www.coolminemotors.ie

VAT Number: IE9754664N



Date:	23/06/2025
Invoice No:	50038

Invoice To:

--

Vehicle Details

Make :	Mazda	Reg. No:	172D19940	Milage:	
Model :	3	Engine:			

Service A.

Description:

		Qty :	Price :
Parts 13.5 %	€88.10		€88.10
Parts 23 %			
Tyres		1	€0.00
Batteries			€0.00
Accessories			€0.00
Labour 13.5 %	€70.49		€70.49
VEMC Charge Car / Van / 4x4	€2.80		€0.00
VAT 13.5 %			€21.41
VAT 23 %			€0.00

Total : €180.00

All goods shall remain the property of MJ Coolmine Motors Limited until paid in full

Included in this is a visible Environmental Management Cost -VEMC

Thank You For Your Business

Coolmine Motors LTD

Unit 46 c Coolmine Industrial Estate

Blanchardstown, Dublin 15

Mobile: 0860488100/0877631513

Phone: 018228436

Email: info@coolminemotors.ieWeb: www.coolminemotors.ie

VAT Number: IE9754664N



Date:	24/06/2025
Invoice No:	50056

Invoice To:

--

Vehicle Details

Make :	Mazda	Reg. No:	172D19940	Milage:	
Model :	3	Engine:			

Description:	RHS rear coil spring, LHS front suspension arm, 2 rear stabiliser links, wheel tracking.
--------------	---

		Qty :	Price :
Parts 13.5 %	€361.24		€361.24
Parts 23 %			
Tyres		1	€0.00
Batteries			€0.00
Accessories			€0.00
Labour 13.5 %	€211.45		€211.45
VEMC Charge Car / Van / 4x4	€0.00		€0.00
VAT 13.5 %			€77.31
VAT 23 %			€0.00

Total :	€650.00
----------------	----------------

All goods shall remain the property of MJ Coolmine Motors Limited until paid in full

Included in this is a visible Environmental Management Cost -VEMC

Thank You For Your Business

Coolmine Motors LTD
Unit 46 c Coolmine Industrial Estate
Blanchardstown, Dublin 15
Mobile: 0860488100/Phone: 018228436
Email: info@coolminemotors.ie
Web: www.coolminemotors.ie
VAT Number: IE9754664N



DATE: 20/06/2024
INVOICE NO 44943

INVOICE

Vehicle Details			
Model: Mazda	Date 172D19940	Milage:	
Model: 3	Engine		
Description Service A.			
Part No:			
	€70.48	1	€70.48
		1	€0.00
		1	€0.00
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
PARTS 23%			
Tyres			
Batteries			
Accessories			
VEMC Charge Car/Van/4x4 Repak Member Number: 3680			
	€2.80		€0.00
LABOUR			
	€70.49	1	€70.49
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
			€0.00
Total			€70.48
Parts 13.5%			€70.49
Labour			€0.00
Parts 23%			€140.97
Total NET 23%			€0.00
VAT 13.5%			€19.03
VAT 23%			€0.00
Total:			€160.00

Make all checks payable to MJ Coolmine Motors Limited
All goods shall remain the property of MJ Coolmine Motors Limited until paid in full.
Included in this price is a visible Environmental Management Cost - VEMC

THANK YOU FOR YOUR BUSINESS

Unit 46 c Coolmine Industrial Estate
Blanchardstown, Dublin 15
Mobile: 0860488100/Phone: 018228436
Email: info@coolminemotors.ie
Web: www.coolminemotors.ie
VAT Number: IE9754664N

INVOICE NC 40574



		Vehicle Details					
Make	Mazda			Reg	172D19940	Milage:	
Model:	3			Engine			
Description Service A							
Paet No:							
			€79.29	1	€79.29		
				1	€0.00		
				1	€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
					€0.00		
	PARTS 23%						
	Tyres						
	Batteries						
	Accsesories				€0.00		
	VEMC Charge Car/Van/4x4 Repak Member Number: 3680		€2.80		€0.00		
	LABOUR				Total		
		€61.68	1	€61.68			
				€0.00			
				€0.00			
				€0.00			
				€0.00			
				€0.00			
				€0.00			
Make all checks payable to MJ Coolmine Motors Limited All goods shall remain the property of MJ Coolmine Motors Limited until paid in full. Included in this price is a visible Environmental Management Cost - VEMC					Parts 13.5%	€79.29	
					Labour	€61.68	
					Parts 23%	€0.00	
						€140.97	
					Total NET 23%	€0.00	
					VAT 13.5%	€19.03	
					VAT 23%	€0.00	
THANK YOU FOR YOUR BUSINESS					Total:	€160.00	

		Vehicle Details					
Make	Mazda			Reg	172D19940	Milage:	
Model:	3			Engine			
Description	Service A, front brake pads						
Paet No:							
			€140.96	1		€140.96	
				1		€0.00	
				1		€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
						€0.00	
		PARTS 23%					
	Tyres						
	Batteries						
	Accsesories						
	VEMC Charge Car/Van/4x4 Repak Member Number: 3680	€2.80			€0.00		
	LABOUR		QTY	Total			
		€105.74	1	€105.74			
				€0.00			
			€0.00				
			€0.00				
			€0.00				
			€0.00				
Make all checks payable to MJ Coolmine Motors Limited All goods shall remain the property of MJ Coolmine Motors Limited until paid in full. Included in this price is a visible Environmental Management Cost - VEMC				Parts 13.5%	€140.96		
				Labour	€105.74		
				Parts 23%	€0.00		
					€246.70		
				Total NET 23%	€0.00		
				VAT 13.5%	€33.30		
VAT 23%	€0.00						
Total:				€280.00			

THANK YOU FOR YOUR BUSINESS

Coolmine Motors LTD
Unit 46 c Coolmine Industrial Estate
Blanchardstown, Dublin 15
Mobile: 0860488100/Phone: 018228436
Email: info@coolminemotors.ie
Web: www.coolminemotors.ie
VAT Number: IE9754664N



DATE:	06/09/2021
INVOICE No	32854

INVOICE

Vehicle Details					
Model:	Mazda	Reg	172d19940	Milage:	44,582 kms
Model:	3	Engine:	1.5p		
Description: Oil (0W20), oil filter, air filter change, Car inspection.					
Part No:				QTY	Total
				€70.48	1
					€70.48
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
PARTS 23%					
Tyres				1	
Batteries					
Accessories					€0.00
VEMC Charge Car/Van/4x4 Repak Member Number: 3680				€2.80	€0.00
LABOUR				QTY	Total
Labour				€52.87	1
					€52.87
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
					€0.00
Parts 13.5%					€70.48
Labour					€52.87
Parts 23%					€0.00
Total NET					€123.35
Total NET 23%					€0.00
VAT 13.5%					€16.65
VAT 23%					€0.00
Total:					€140.00

Make all checks payable to MJ Coolmine Motors Limited
All goods shall remain the property of MJ Coolmine Motors Limited until paid in full.
Included in this price is a visible Environmental Management Cost - VEMC

THANK YOU FOR YOUR BUSINESS

Mazda Digital Service Record



Vehicle Details

Mazda3 - 1.5L SKYACTIV-G (100
hp) - 6MT

Model - Engine - Transmission

29/09/2017

Warranty Start Date

Soul Red
Paint Colour

172D19940

License Plate

Ireland

Country of Origin

Customer Details

Mr Ata Sasmaz

Dublin

City

CO DUBLIN

County

Ireland

Country

+353894678557

Contract Overview

Mazda Europe Service

Optional Extended Warranty

Service Activated Warranty

Used Car Warranty

Standard cover expired - please discuss with your Mazda dealer

No coverage

No coverage

No coverage

Next Scheduled Visit Due

Adjusted Intervals

Please note: SKYACTIV Technology uses actual driving conditions to calculate the next required service and displays it on your vehicle's system. Wrench indication light will illuminate 1.000 km or 15 days before the necessary service". Estimation values below.

Service Intervals

Flexible maintenance indication the latest every 20.000 km (12.500 miles) or 12 months (whichever comes first)

Your Manufacturer or Optional Extended Warranty may be affected if the recommended service schedule is not followed.

Next Scheduled Service Due

4th Service

Expected at

41949 Km or 27/08/2021

Latest at

52725 Km or 04/09/2021 (whichever comes first)

Previous Visits

Job Info

Odometer

Services Completed



MMIRL, JOE DUFFY MAZDA
Exit 5 M50
North Road
IE - D11 V21K Dublin
+35318503904

04/09/2020
39024

32725 Km

60.000 km / 37.500 miles / 3th
Year
Body Inspection



MMIRL, JOE DUFFY MAZDA
Exit 5 M50
North Road
IE - D11 V21K Dublin
+35318503939

13/09/2019
32981

23501 Km

40.000 km / 25.000 miles / 2nd
Year
Body Inspection



* The DSR Helpdesk made this
entry for an Independent
Operator See 'Job N
GB - Tunbridge TN4 8BS

13/09/2018
Joe Duffy Mazda

6921 Miles

20.000 km / 12.500 miles / 1st
Year



Mazda Digital Service Record



Previous Visits	Job Info	Odometer	Services Completed
 MMIRL, J A BOLAND (CARLOW) LIMITED Dublin Road IE - R93AV24 Carlow +353599140077	11/09/2017 0000 	8 Km	PDI Body Inspection 

Icon Legend



Mazda Summer Check



Visual Health Check



Renewal of Cabin Air Filter



Renewal of Engine Air Filter




Renewal of Oil and Oil Filter



NCT CERTIFICATE

TEASTAS NCT



23-09-2021

It is hereby certified that the vehicle described in this Certificate was tested on in accordance with the Road Traffic (National Car Test) Regulations and was found to comply therewith.

Deimhnítear leis seo gur tástáladh an fheithicil a chuirtear síos uirthi sa Teastas seo ar an 23-09-2021 de réir na Rialachán um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán) agus go gcloíonn an fheithicil leis na rialacháin chéanna.

PARTICULARS/SONRAÍ

- VIN:
Uimhir UTF:
- Registration Number: **172D19940** IRL
Uimhir Chláraithe:
- Place and Date of Test: **Fonthill 23-09-2021**
Áit agus Dáta na tástála:
- Odometer Reading: **44864km** Date **23-09-2021**
Léamh Odaiméadair: Dáta
- Odometer Reading: Date
Léamh Odaiméadair: Dáta
- Odometer Reading: Date
Léamh Odaiméadair: Dáta
- Odometer Reading: Date
Léamh Odaiméadair: Dáta
- Vehicle Category: **M1** 6. Identified Deficiencies: **Refer to the Vehicle Inspection Report**
Catagóir na feithicle: Easnaimh a tugadh:
- Test Result: **Pass** 8. Expiry Date: **28-09-2023**
Toradh Tástála: Dáta Eaga:
- NCT Centre ID and Tester ID: **18 AF**
Ionad NCT ID agus Tástálaí ID:
- Other Information: Make: **MAZDA** Model: **3**
Eolas Eile: Déantús: Cineál:
- Colour: **RED** Date of First Registration: **29-09-2017**
Dath: Dáta a Chéadchláraíodh:

E 4902692

E 4902692

The NCT Disc on the right is required by law to be displayed on the inside of your vehicle windscreen.

Ní mór, de réir dlí, an Dísca NCT ar dheis a thaispeáint ar an taobh istigh de ghaothscáth d'fheithicle.

This Certificate should be kept in a safe place. It must be presented as proof that you have complied with the Road Traffic (National Car Test) Regulations.

Ba chóir an Teastas seo a choinneáil in áit shábháilte. Fianaise is ea é gur chloígh tú leis na Rialacháin um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán).

This Certificate relates only to the condition of testable items at the time of test. This Certificate should not be regarded as a warranty, express or implied under common law or at all.

Níl aon léargas sa Teastas seo ach ar staid éarrat intástála ag am a dtástála. Ná tuigtear gur Barántas atá ann, bíodh sin sainráite nó intuigthe faoi bhun reachtaíochta nó an dlí choitinn nó in aon chor.



180051789983

23-09-2021

28-09-23

172D19940

44864km

PRIVATE CO2

MAZDA

3

2017



NCT Report: PASS ADVISORY

Visit www.ncts.ie to book your full test or retest online and select a date and time that suits you.

Vehicle/Owner Details

Test Started On: 23-Sep-2021 10:41:10

Owner: MR ATA SASMAZ

Registration: 172D19940

Vin: XXXXXXXXXX

Manufacturer: MAZDA

Model: 3

Please Check Odometer Reading!

Any corrections must be notified immediately to a member of staff before leaving the centre, as the recorded mileage cannot be changed afterwards.

Odometer: 44,864km Date 23-09-2021

Item Modification Report Date

OBD Odometer:

OBD Vin:

Test Readings

Side-slip/Alignment Test

		Failing Limits	Result
Front Axle	0.0 m/Km	Outside +14 to -14(m/km)	PASS
Rear Axle	-3.0 m/Km	Outside +18 to -18(m/km)	PASS

Suspension	Nearside	Offside	Imbalance	Failing Limits	Result
Front Axle	28 Mm	26 Mm	7 %	Imbalance Above 30%	PASS
Rear Axle	31 Mm	33 Mm	6 %	Imbalance Above 30%	PASS

Brake	Brake Effort		Ovality		Imbalance	Failing Limits		Result
	Nearside	Offside	Nearside	Offside				
Front Axle	3.010 kN	3.160 kN	0 %	0 %	5 %	Performance less than	58 %	PASS
Rear Axle	2.110 kN	2.130 kN	6 %	7 %	1 %	Front Imbalance Above	30 %	
Service Brake Performance	80 %					Rear Imbalance Above	30 %	
						Ovality above	90 %	
Car Weight	1,320 Kg							
Parking Brake	1.640 kN	1.770 kN			7 %	Parking Imbalance Above	50 %	PASS
Parking Brake Performance	26 %					Performance less than	16 %	

Exhaust Emissions

		Failing Limits	Result
		Limits depend on Year of Manufacture	
Low Idle	Engine/Oil Temperature 80 °C		
(560 rpm)	CO 0.01 vol%	Above 0.30 %	PASS
	HC 102 ppm	Above 0 ppm	N/A
High Idle	Lambda: 1.00	Not between 0.97 and 1.03	PASS
(2,750 rpm)	CO 0.05 vol%	Above 0.20 %	PASS
	HC 141 ppm	Above 200 ppm	PASS

Lights	Nearside	Offside	Result
Dip Beam	PASS	PASS	PASS
Full Beam	N/A	N/A	
Fog Light	N/A	N/A	
Aux. Light	N/A	N/A	

Visual Defects

Item	Description	Reason	Location	
Service Brake Operation	Anti-lock system	Communication failure with electronic vehicle interface		ADVISORY


OBD Faults

Item	OBD Code	Description	Location
------	----------	-------------	----------



NCT CERTIFICATE

TEASTAS NCT



20-07-2023

It is hereby certified that the vehicle described in this Certificate was tested on in accordance with the Road Traffic (National Car Test) Regulations and was found to comply therewith.

Deimhnítear leis seo gur tástáladh an fheithicil a chuirtear síos uirthi sa Teastas seo ar an 20-07-2023 de réir na Rialachán um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán) agus go gcloíonn an fheithicil leis na rialacháin chéanna.

PARTICULARS/SONRAÍ

- VIN: 
Uimhir UTF:
- Registration Number: **172D19940** IRL
Uimhir Chláraithe:
- Place and Date of Test: **Navan 20-07-2023**
Áit agus Dáta na tástála:
- Odometer Reading: **62350km** Date **20-07-2023**
Léamh Odaiméadair: Dáta
- Odometer Reading: **44864km** Date **23-09-2021**
Léamh Odaiméadair: Dáta
- Odometer Reading: Date
Léamh Odaiméadair: Dáta
- Odometer Reading: Date
Léamh Odaiméadair: Dáta
- Vehicle Category: **M1** 6. Identified Deficiencies: **Refer to the Vehicle Inspection Report**
Catagóir na feithicle: Easnaimh a tugadh:
- Test Result: **Pass** 8. Expiry Date: **28-09-2025**
Toradh Tástála: Dáta Eaga:
- NCT Centre ID and Tester ID: **52 DO**
Ionad NCT ID agus Tástálaí ID:
- Other Information: Make: **MAZDA** Model: **3**
Eolas Eile: Déantús: Cineál:
- Colour: **RED** Date of First Registration: **29-09-2017**
Dath:  Dáta a Chéadchláraíodh:

The NCT Disc on the right is required by law to be displayed on the inside of your vehicle windscreen.


Ní mór, de réir dlí, an Diosca NCT ar dheis a thaispeáint ar an taobh istigh de ghaothscáth d'fheithicle.

This Certificate should be kept in a safe place. It must be presented as proof that you have complied with the Road Traffic (National Car Test) Regulations.

Ba chóir an Teastas seo a choinneáil in áit shábháilte. Fianaise is ea é gur chloigh tú leis na Rialacháin um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán).

This Certificate relates only to the condition of testable items at the time of test. This Certificate should not be regarded as a warranty, express or implied under common law or at all.

Níl aon léargas sa Teastas seo ach ar staid éarrat intástála ag am a dtástála. Ná tuigtear gur Barántas atá ann, bíodh sin sainráite nó intuigthe faoi bhun reachtaíochta nó an dlí choitinn nó in aon chor.



520054311007

20-07-2023

28-09-25

172D19940

62350km

PRIVATE C02

MAZDA

3

2017



NCT Report: PASS ADVISORY

Visit www.ncts.ie to book your full test or retest online and select a date and time that suits you.

Vehicle/Owner Details				Test Started On: 20-Jul-2023 15:59:11	
Owner:	MR ATA SASMAZ	Please Check Dashboard Odometer Reading! Any corrections must be notified immediately to a member of staff before leaving the centre, as the recorded mileage cannot be changed afterwards.	Odometer: 62,350km		Date 20-07-2023
Registration:	172D19940		Item	Modification Report	Date
Vin:					
Manufacturer:	MAZDA				
Model:	3	OBD Odometer:	OBD Vin:		

Test Readings

Side-slip/Alignment Test		Failing Limits		Result
Front Axle	-1.0 m/Km	Outside	+14 to -14(m/km)	PASS
Rear Axle	-4.0 m/Km	Outside	+18 to -18(m/km)	PASS

Suspension	Nearside	Offside	Imbalance	Failing Limits	Result
Front Axle	29 Mm	27 Mm	7 %	Imbalance Above 30%	PASS
Rear Axle	34 Mm	35 Mm	3 %	Imbalance Above 30%	PASS

Brake	Brake Effort		Ovality		Imbalance	Failing Limits	Result
	Nearside	Offside	Nearside	Offside			
Front Axle	3.230 kN	3.400 kN	10 %	9 %	5 %	Performance less than 58 %	PASS
Rear Axle	1.990 kN	2.030 kN	5 %	6 %	2 %	Front Imbalance Above 30 %	
Service Brake Performance	84 %					Rear Imbalance Above 30 %	
						Ovality above 90 %	
Car Weight	1,290 Kg						
Parking Brake	1.540 kN	1.740 kN			11 %	Parking Imbalance Above 50 %	PASS
Parking Brake Performance	26 %					Performance less than 16 %	

Exhaust Emissions		Failing Limits		Result
		Limits depend on Year of Manufacture		
Engine/Oil Temperature 65 °C				
Low Idle	CO 0.00 vol%	Above	0.30 %	PASS
(560 rpm)	HC 3 ppm	Above	0 ppm	N/A
High Idle	Lambda: 1.01	Not between	0.97 and 1.03	PASS
(2,740 rpm)	CO 0.00 vol%	Above	0.20 %	PASS
	HC 2 ppm	Above	200 ppm	PASS

Lights	Nearside	Offside	Result
Dip Beam	PASS	PASS	PASS
Full Beam	N/A	N/A	
Fog Light	N/A	N/A	
Aux. Light	N/A	N/A	


Visual Defects				
Item	Description	Reason	Location	
Tyre Condition	Age	More than 6 years old	Offside Rear	ADVISORY
Tyre Condition	Age	More than 6 years old	NearsideRear	ADVISORY

OBD Faults				
Item	Code	Description	Location	Type



NCT CERTIFICATE

TEASTAS NCT



It is hereby certified that the vehicle described in this Certificate was tested on **23-07-2025** in accordance with the Road Traffic (National Car Test) Regulations and was found to comply therewith.

Deimhnítear leis seo gur tástáladh an fheithicil a chuirtear síos uirthi sa Teastas seo ar an **23-07-2025** de réir na Rialachán um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán) agus go gcloíonn an fheithicil leis na rialacháin chéanna.

PARTICULARS/SONRAÍ

- VIN:
Uimhir UTF:
- Registration Number: **172D19940** IRL
Uimhir Chláraithe:
- Place and Date of Test: **Fonthill 23-07-2025**
Áit agus Dáta na tástála:
- Odometer Reading: **78336km** Date **23-07-2025**
Léamh Odaiméadair: Dáta
- Odometer Reading: **62350km** Date **20-07-2023**
Léamh Odaiméadair: Dáta
- Odometer Reading: **44864km** Date **23-09-2021**
Léamh Odaiméadair: Dáta
- Odometer Reading:
Léamh Odaiméadair: Dáta
- Vehicle Category: **M1** 6. Identified Deficiencies: **Refer to the Vehicle Inspection Report**
Catagóir na feithicle: Easnamh a tugadh:
- Test Result: **Pass** 8. Expiry Date: **28-09-2027**
Toradh Tástála: Dáta Eaga:
- NCT Centre ID and Tester ID: **18 SB**
Ionad NCT ID agus Tástálaí ID:
- Other Information: Make: **MAZDA** Model: **3**
Eolas Eile: Déantús: Cineál:
- Colour: **RED** Date of First Registration: **29-09-2017**
Dath: Dáta a Chéadchláraíodh:

G 3578736

G 3578736



The NCT Disc on the right is required by law to be displayed on the inside of your vehicle windscreen.

Ní mór, de réir dlí, an Diosca NCT ar dheis a thaispeáint ar an taobh istigh de ghaothscáth d'fheithicle.

This Certificate should be kept in a safe place. It must be presented as proof that you have complied with the Road Traffic (National Car Test) Regulations.

Ba chóir an Teastas seo a choinneáil in áit shábháilte. Fianaise is ea é gur chloígh tú leis na Rialacháin um Thrácht ar Bhóithre (An Trialacháin Náisiúnta Ghluaisteán).

This Certificate relates only to the condition of testable items at the time of test. This Certificate should not be regarded as a warranty, express or implied under common law or at all.

Níl aon léargas sa Teastas seo ach ar staid éarrat intástála ag am a dtástála. Ná tuigtear gur Barántas atá ann, bíodh sin sainráite nó intuigthe faoi bhun reachtaíochta nó an dlí choitinn nó in aon chor.

180057515734

23-07-2025

28-09-27

172D19940

78336km

PRIVATE CO2

MAZDA

3

2017



NCT Report: PASS ADVISORY

Visit www.ncts.ie to book your full test or retest online and select a date and time that suits you.

Vehicle/Owner Details				Test Started On: 23-Jul-2025 12:04:53	
Owner:	MR ATA SASMAZ	Please Check Dashboard Odometer Reading! Any corrections must be notified immediately to a member of staff before leaving the centre, as the recorded mileage cannot be changed afterwards.	Odometer: 78,336km		Date 23-07-2025
Registration:	172D19940		Item	Modification Report	Date
Vin:					
Manufacturer:	MAZDA				
Model:	3	OBD Odometer:	78,336 km	OBD Vin:	

Test Readings

Side-slip/Alignment Test			Failing Limits		Result
Front Axle	-1.0 m/Km		Outside	+14 to -14(m/km)	PASS
Rear Axle	0.0 m/Km		Outside	+18 to -18(m/km)	PASS

Suspension	Nearside	Offside	Imbalance	Failing Limits	Result
Front Axle	31 Mm	31 Mm	0 %	Imbalance Above 30%	PASS
Rear Axle	37 Mm	38 Mm	3 %	Imbalance Above 30%	PASS

Brake	Brake Effort		Ovality		Imbalance	Failing Limits	Result
	Nearside	Offside	Nearside	Offside			
Front Axle	3.310 kN	3.320 kN	58 %	59 %	0 %	Performance less than 58 %	PASS
Rear Axle	1.910 kN	2.110 kN	34 %	37 %	9 %	Front Imbalance Above 30 %	
Service Brake Performance	84 %					Rear Imbalance Above 30 %	
Car Weight	1,292 Kg					Ovality above 90 %	PASS
Parking Brake	1.140 kN	1.640 kN			30 %	Parking Imbalance Above 50 %	
Parking Brake Performance	22 %					Performance less than 16 %	

Exhaust Emissions			Failing Limits		Result
Engine/Oil Temperature 99 °C			Limits depend on Year of Manufacture		
Low Idle	CO 0.01 vol%		Above	0.30 %	PASS
(740 rpm)	HC 89 ppm		Above	0 ppm	N/A
High Idle	Lambda: 1.00		Not between	0.97 and 1.03	PASS
(3,130 rpm)	CO 0.01 vol%		Above	0.20 %	PASS
	HC 135 ppm		Above	200 ppm	PASS

Lights	Nearside	Offside	Result
Dip Beam	PASS	PASS	PASS
Full Beam	N/A	N/A	
Fog Light	N/A	N/A	
Aux. Light	N/A	N/A	

Visual Defects				
Item	Description	Reason	Location	
Tyre Condition	Age	More than 6 years old	Offside Rear	ADVISORY
Tyre Condition	Age	More than 6 years old	NearsideRear	ADVISORY
Tyre Tread	Depth of Tread Less than 3.00mm	Worn	NearsideRear	ADVISORY

OBD Faults				
Item	Code	Description	Location	Type